



### **Becker Traffic Assist Z 203**

- Soundsystem fixes
- Support for Pay TMC
- fixed - minor problem when entering greek addresses with latin letters
- first Bluetooth initializing issue fixed
- minor fixes at Traffic patterns
- minor fixes at TMC
- Select POI categories saved if you press Back or OK
- fixed - loop of the speed limit warning during more than 3 minutes.
- fixed - never ending route recalculated announcement
- fixed - Iphone pairing problem
- fixed - different volume of TTS and non TTS
- Street first - Street search without city for US and Australia
- fixed - Phone: "Delete all Pairing" does not remove list of paired phones
- Minor Bluetooth issues fixed
- fixed - speedlimit warning too early
- Various minor and cosmetic bugfixes

### **Becker Traffic Assist Z 204**

- Soundsystem fixes
- Support for Pay TMC
- fixed - minor problem when entering greek addresses with latin letters
- first Bluetooth initializing issue fixed
- minor fixes at Traffic patterns
- minor fixes at TMC
- Select POI categories saved if you press Back or OK
- fixed - loop of the speed limit warning during more than 3 minutes.
- fixed - never ending route recalculated announcement
- fixed - Iphone pairing problem
- fixed - different volume of TTS and non TTS
- Street search without city for US and Australia
- fixed - Phone: "Delete all Pairing" does not remove list of paired phones
- Minor Bluetooth issues fixed
- fixed - speedlimit warning too early
- Various minor and cosmetic bugfixes

### **Becker Traffic Assist Z 205**

- Soundsystem fixes
- fixed - minor problem when entering greek addresses with latin letters
- first Bluetooth initializing issue fixed
- minor fixes at Traffic patterns
- minor fixes at TMC
- Select POI categories saved if you press Back or OK
- fixed - loop of the speed limit warning during more than 3 minutes.
- fixed - never ending route recalculated announcement
- fixed - Iphone pairing problem
- fixed - different volume of TTS and non TTS
- Street search without city for US and Australia
- fixed - Phone: "Delete all Pairing" does not remove list of paired phones
- Minor Bluetooth issues fixed
- fixed - speedlimit warning too early
- Various minor and cosmetic bugfixes